



SCANWOOD

SOLUTIONS (pty) Ltd

TIMBER PROCESSING • AGRICULTURE • BIO-ENERGY

Troubleshooting for TP100

Problem / Possible Cause	Solution
The chip quality is not satisfactory	
<ol style="list-style-type: none"> 1. The blades are blunt 2. The anvil is worn 3. The blades have been blunted & sharpened too many times (less than 28mm) 4. Distance between blades & anvil too wide 	<ol style="list-style-type: none"> 1. Sharpen blades 2. Rotate / replace anvil 3. Replace blades 4. Adjust distance between blades & anvil
Poor ejection of chips from spout	
<ol style="list-style-type: none"> 1. Too little drive 2. Not enough rpm on the machine 3. Drive belts too slack / worn 	<ol style="list-style-type: none"> 1. Insufficient power on the PTO shaft or engine 2. Increase speed to maximum revs 3. Adjust belts / change the belts
Engine problems	
Mobile models	See users manual for Briggs & Stratton engines